

# Oil Field Environmental Incident Summary

**Incident:** 20150306151127 **Date/Time of Notice:** 03/06/2015 15:11

**Responsible Party:** DENBURY ONSHORE, LLC

**Well Operator:** DENBURY ONSHORE, LLC

**Well Name:** US 3-11F

**Field Name:** T. R.

**Well File #:** 6919

**Date Incident:** 3/6/2015 **Time Incident:** 07:00

**Facility ID Number:**

**County:** BILLINGS

**Twp:** 141

**Rng:** 101

**Sec:** 11

**Qtr:**

**Location Description:** All standing fluid on location with a 3-5 gallon misting impact in an area approximately 100 ft by 80 ft off location.

**Submitted By:** Josh Cuppy

**Received By:**

**Contact Person:** Brian Ehrmantraut  
5320 LEGACY DR  
PLANO, TX 75024-3127

**General Land Use:** Badlands Terrain

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 5 Mile

**Distance Nearest Water Well:** 5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

|       | Spilled | Units   | Recovered | Units   | Followup | Units   |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil   | 70      | Barrels | 70        | Barrels | 70       | barrels |
| Brine | 50      | Barrels | 50        | Barrels | 50       | barrels |

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/25/2016

**Clean Up Concluded:** 3/26/2015

**Risk Evaluation:**

None

**Areal Extent:**

All was contained within the dike except for 3-5 GALLONS that was misted over an area 100' x 80'.

**Potential Environmental Impacts:**

Very minimal misting.

**Action Taken or Planned:**

The well was shut in and the recycle and burner were turned off. A vac truck was immediately dispatched to suck up the standing fluid. 120 total bbls of fluid was spilled and 120 bbls was recovered and pumped into the facility tanks. The stained ground will be washed with warm fresh water and sucked up with a vac truck. The USFS will determine a cleanup plan for the misted area outside the dikes. The contaminated soil will be excavated and hauled to an approved landfill.

**Wastes Disposal Location:** Approved landfill

**Agencies Involved:** Forest Service

**Updates**

---

**Date:** 3/6/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. However, this spill is also on USFS property. Followup is necessary to ensure sprayed area did not impact any waterways.

---

**Date:** 4/10/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 10:33 a.m. The weather was clear and 46°F, with the wind from the southeast at 5-10 mph. The area just on the east side of the treater and dike has been scraped up. This area is flat; just to the east is very steep badlands terrain. I could not see anything further east of flat area. The site is located in the Grasslands, U.S. Forest Service has oversight. 47.04692; - 103.43890